Recommended Conditions for PEI Matrix CFRTP Heat & Cool Press

[Preparation: Drying]

• 150 °C /2 hours

Temperature & Pressure condition

• Heating pressure: 0.01-0.5MPa

Molding temperature: 340±20°C (K71), 320±20°C (K72)

• Heating pressure: 2.5-5MPa

• Pressure hold time: 10-30min

• Cooling pressure: 2.5-10MP

• Cooling rate: 1-100°C/min

^{*} If there is excessive resin flow, you may shorten the heating time or reduce the heating pressure.

